



UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
09/967,093	09/28/2001	Kirk D. Brannock	042390.P11898	6662
7590 12/02/2005			EXAMINER	
R. Alan Burnett			VO, TED T	
BLAKELY, SO	KOLOFF, TAYLOR & :	ZAFMAN LLP	· .	
Seventh Floor			ART UNIT	PAPER NUMBER
12400 Wilshire Boulevard			2191	
Los Angeles, CA 90025-1026			DATE MAILED: 12/02/2005	

Please find below and/or attached an Office communication concerning this application or proceeding.

	Application No.	Applicant(s)			
	09/967,093	BRANNOCK ET AL.			
Office Action Summary	Examiner	Art Unit			
	Ted T. Vo	2191			
The MAILING DATE of this communication app Period for Reply	ears on the cover sheet with the c	correspondence address			
A SHORTENED STATUTORY PERIOD FOR REPLY WHICHEVER IS LONGER, FROM THE MAILING DA - Extensions of time may be available under the provisions of 37 CFR 1.13 after SIX (6) MONTHS from the mailing date of this communication. - If NO period for reply is specified above, the maximum statutory period w - Failure to reply within the set or extended period for reply will, by statute, Any reply received by the Office later than three months after the mailing earned patent term adjustment. See 37 CFR 1.704(b).	ATE OF THIS COMMUNICATION 36(a). In no event, however, may a reply be ting will apply and will expire SIX (6) MONTHS from a cause the application to become ABANDONE	N. The mety filed In the mailing date of this communication. ED (35 U.S.C. § 133).			
Status					
1) Responsive to communication(s) filed on 15 Se	eptember 2005.				
· · · · · · · · · · · · · · · · · · ·	action is non-final.				
3) Since this application is in condition for allowar	<u>-</u>				
closed in accordance with the practice under E	x parte Quayle, 1935 C.D. 11, 4	53 O.G. 213.			
Disposition of Claims					
4) Claim(s) 1-29 is/are pending in the application. 4a) Of the above claim(s) is/are withdrawn from consideration.					
5) Claim(s) is/are allowed.					
6)⊠ Claim(s) <u>1-6,8-13,15-25 and 27-29</u> is/are rejected.					
7)⊠ Claim(s) <u>7,14,26</u> is/are objected to.					
8) Claim(s) are subject to restriction and/or	r election requirement.				
Application Papers					
9) ☐ The specification is objected to by the Examine 10) ☑ The drawing(s) filed on 28 September 2001 is/a Applicant may not request that any objection to the Replacement drawing sheet(s) including the correct 11) ☐ The oath or declaration is objected to by the Ex	are: a)⊠ accepted or b)⊡ object drawing(s) be held in abeyance. Se ion is required if the drawing(s) is ob	e 37 CFR 1.85(a). ojected to. See 37 CFR 1.121(d).			
Priority under 35 U.S.C. § 119					
12) Acknowledgment is made of a claim for foreign a) All b) Some * c) None of: 1. Certified copies of the priority documents 2. Certified copies of the priority documents 3. Copies of the certified copies of the priority application from the International Bureau * See the attached detailed Office action for a list	s have been received. s have been received in Applicat rity documents have been receiv u (PCT Rule 17.2(a)).	ion No ed in this National Stage			
Attachment(s)					
Notice of References Cited (PTO-892) Notice of Draftsperson's Patent Drawing Review (PTO-948)	4) ☐ Interview Summary Paper No(s)/Mail D				
3) Information Disclosure Statement(s) (PTO-1449 or PTO/SB/08) Paper No(s)/Mail Date		Patent Application (PTO-152)			
S. Patent and Trademark Office					

Application/Control Number: 09/967,093

Art Unit: 2191

DETAILED ACTION

Page 2

1. This action is in response to the filing on 09/15/2005.

Claims 1-29 are pending in the application.

Response to Amendment

2. Applicants' amendment and arguments have been fully considered, but are moot in view of the new ground of rejection presenting in this action.

Claim Objections

3. The verb "are" appeared in lines 5, 9, 10 of claim 1 should be "is". Claim 15 requires the ending period ".". Typo checking in the Claims would be required.

Claim Rejections - 35 USC § 102

4. The following is a quotation of the appropriate paragraphs of 35 U.S.C. 102 that form the basis for the rejections under this section made in this Office action:

A person shall be entitled to a patent unless -

- (b) the invention was patented or described in a printed publication in this or a foreign country or in public use or on sale in this country, more than one year prior to the date of application for patent in the United States.
- 5. Claim 1-6, 8-13, 15-25, 27-29 are rejected under 35 U.S.C. 102(b) as being anticipated by IBM, "A Technical Introduction to PCI-Based RS/6000 Servers", 1996.

Given the broadest reasonable interpretation of followed claims in light of the specification.

As per Claim 1: IBM discloses a method for updating an existing portion of platform firmware data, With regards to the limitation,

writing updated firmware data that is to replace the existing portion of platform firmware data to a firmware storage device in which the existing portion of firmware are stored

See sec. 4.4.3, (p.67) IBM discloses writing update firmware to replace an existing firmware in a ROM(defined as first code in sec. 4.2.1, p.56) or in the sectors in the NVRAM that is latter updated. The PCI-Based RS/6000 is such a platform firmware data.

With regards to the limitation

atomically modifying firmware configuration data in the firmware storage device to indicate the updated firmware data is to be used in place of the existing portion of platform firmware data that is being updated such that only the existing portion of platform firmware data are valid prior to the atomic modification of the firmware configuration data and only the updated firmware data are valid after the atomic modification to the firmware configuration data

First of all, the Figures in the IBM's reference (such as Figure 24 (p.63)) show firmware configuration data. IBM discloses atomically modifying firmware configuration data where firmware data is loaded only onto firmware sectors in the memory (See p. 58, Figure 20, an NVRAM, and see p. 61, Figure 22, showing mapped Memory structure of RR/6000 where firmware is stored). The firmware in the sectors is examined (valid) and whether it needs to update (sec. 4.4.3, p.67).

As per Claim 2: Regarding limitation: The method of claim 1, further comprising performing an integrity check of the updated firmware data to verify that the updated firmware data is valid., IBM provides CRC check (See sec.4.4.4, p.68)

As per Claim 3: Regarding limitation: The method of claim 1, wherein the updated firmware data is written to the firmware storage device in a manner in which the updated firmware data is invisible to a firmware management system used to access firmware data stored on the firmware storage device until the atomic modification of the firmware configuration data has been made., IBM remains teach this claimed limitation

Art Unit: 2191

because all code stored in a storage is invisible to its System Management Service unless it is visually accessed by a tool editor.

As per Claim 4: Regarding limitation: The method of claim 1, further comprising enabling a full recovery of the existing portion of firmware data that is to be updated during an upgrade process in response to a system anomaly that prevents completion of the upgrade process., IBM provides Firmware recovery (See sec. 4.4.4, p. 68).

As per Claim 5: Regarding limitation: The method of claim 1, further comprising deleting the existing portion of platform firmware after it has been upgraded., IBM remains teaching this limitation because the means of update is to replace the unwanted code. Therefore the code must be discarded. As seen in the sec. 4.4.3, (p.67), updated firmware is loaded onto sectors that have original firmware, or using the cleanup.

As per Claim 6: Regarding limitation: The method of claim 1, wherein the existing platform firmware data and the updated firmware data respectively comprise one or more firmware files, each firmware file including header data that are modified during the update process to track a current state of that file.

See the structure of the Boot image (Figures 22, 24, that present firmware files), having header.

As per Claim 8: Regarding limitation: The method of claim 1, wherein the firmware storage device comprises a flash memory device.

Flash memory device is only a memory, all the memory such as NVRAM is includes this feature. For example, IBM (p. 67, sec 4.4.3) says "Firmware Flash Update", in sec. 4.4.4, it says "to rewrite the Flash memory".

As per Claim 9: IBM discloses a method for atomically updating a plurality of existing platform firmware files:

With regards to limitation:

creating a temporary file in a firmware storage device in which the existing platform firmware files are stored; (See definition Firmware in section 4.2.1: Active RAM area: 'creating a temporary file in a firmware storage device');

writing data corresponding to a plurality of updated platform firmware files comprising new versions of the plurality of existing platform firmware files to the temporary file; (See definition Firmware in section 4.2.1: See sec. 4.4.3, (p.67) and 4.4.4, IBM discloses writing update firmware into a flash memory to replace an existing firmware (defined as first code in sec. 4.2.1, p.56) in the platform firmware data such as the PCI-Based RS/6000.

and atomically modifying platform firmware file configuration information to indicate that the updated platform firmware files are to be used in place of the existing platform firmware files such that only the existing platform firmware files or only the updated platform firmware files are valid at any point in time during an update process.

IBM's reference (such as Figure 24 (p.63)) shows firmware configuration data such as in the memory structure. IBM discloses atomically modifying firmware configuration data where firmware data is loaded only onto firmware sectors in the memory (flash memeory)(See p. 58, Figure 20, an NVRAM, and see p. 61, Figure 22, showing mapped Memory structure of RR/6000 where firmware is stored). The firmware in the sectors is examined (valid) and whether it needs to update (sec. 4.4.3, p.67).

As per Claim 10: IBM discloses

each platform firmware file comprises a file header and a data area in which platform firmware data corresponding to that file is written, and wherein each file header includes a plurality of state bits that are used to track a current state of each platform firmware file during the update process.,

in the Boot image structure (Figures 20, 22, 24, that present firmware files), having a "header" partition table that is used in order to track the firmware in the sectors.

As per Claim 11: IBM discloses.

wherein the temporary file is created by creating a file header that identifies the temporary file includes a data area that is sized to hold all of the updated platform firmware files, said data area being mapped to a memory area on a firmware storage device that is used to store the existing and updated platform firmware files. See definition "Firmware" in section 4.2.1 and see the "header" partition table (Figures 22, 24) that is used in order to track and to locate valid firmware in the sectors

Page 6

As per Claim 12: IBM discloses. The method of claim 11, further comprising changing a state bit in the temporary file's file header to indicate that the temporary file is invalid after data corresponding to the updated platform firmware files are written to the data area of the temporary file.

See IBM definition "Firmware", Original firmware is stored in the ROM that is read only. The table header is located in a flash area and used to locate the valid firmware. Therefore, every firmware updated code must not be in the ROM, where the header is used to locate the updated firmware in the RAM or in a flash memory, rather than the code in the ROM.

As per Claim 13: Regarding,

a file system is used to access the platform firmware files and the updated firmware files appear invisible to the file system prior to when the state bit is changed and become visible to the file system after the state bit is changed.,

IBM remains teach this claimed limitation because all code stored in a storage is invisible to its System Management Service unless it is visually accessed by a tool editor for modifying.

As per Claim 15: Regarding, further comprising performing an integrity check of the updated platform firmware files to verify that the updated firmware files are valid prior to atomically modifying the platform firmware file configuration information to indicate that the updated platform firmware files are to be used in place of the existing platform firmware.,

IBM provides CRC check.

As per Claim 16: Regarding, The method of claim 9, further comprising enabling a full recovery of the existing platform firmware files that are to be updated during the upgrade process in response to a system anomaly that prevents completion of the upgrade process.

IBM provides recovery as shown in the rationale related to the rejection of Claims 1-6, 8.

As per Claim 17: Regarding, The method of claim 10, further comprising setting the state bits in each file header of the existing platform firmware files to indicate the file is deleted after the upgrade process has been complete.

IBM provides clean-up as shown in the rationale related to the rejection of Claims 1-6, 8.

As per Claim 18: The functionality in Claim 18 is corresponding to the limitation recited in Claim 1. See rationale addressed in Claim 1 above.

As per Claim 19: The functionality in Claim 19 is corresponding to the limitation recited in Claim 2. See rationale addressed in Claim 2 above.

As per Claim 20: The functionality in Claim 18 is corresponding to the limitation recited in Claim 4. See rationale addressed in Claim 4 above.

As per Claims 21-25, 27-29: Each functionality in Claims 21-25, 27-29 is corresponding to the limitation recited in Claims 9-13, respectively. See rationale addressed in Claims 9-13 above.

Allowable Subject Matter

6. Claims 7, 14, 26 remain allowable as given in the prior action.

Conclusion

7. Any inquiry concerning this communication or earlier communications from the examiner should be directed to Ted T. Vo whose telephone number is (571) 272-3706. The examiner can normally be reached on 8:00AM to 5:30PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Wei Y. Zhen can be reached on (571) 272-3708.

The facsimile number for the organization where this application or proceeding is assigned is the Central Facsimile number **571-273-8300**.

Any inquiry of a general nature or relating to the status of this application should be directed to the TC 2100 Group receptionist: 571-272-2100. Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR

Art Unit: 2191

system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

Ted T. Vo

Primary Examiner

Art Unit 2191

November 22, 2005